

## **STYLE P50**

### Carbon fibre with special Graphite Impregnation and silicon free Run In lubricant



	*	J	ب <b>ل</b> م							
p [bar]	25	100	100							
v [m/s]	20	2	-							
t ⁰C	-50 +250 (200*)									
pН	2 - 12									
pH g/cm <sup>3</sup>	1.15									

### Form of delivery:

This packing can be manufactured from 4 to 30 mm square as well as in intermediate, inch sizes and special measurements.

04 - 09 mm 10 - 15 mm 16 mm and above			on on on	2.5 I 5 kg	spool <g spool<br="">spool</g>		Special length, pre-cut or die formed rings on request.													00/00
1	kg of pack	ing of th	ne follow	ing cros	s-sectio	ns is equ	uivalent <sup>-</sup> 3/8"	to displ	ayed metr	re leng	ths: 1/2"	14	15	16	18	19	20	22	25	
	[m]	54	34,8	24,2	21,6	13,6	9,6	8,7	7,2	6	5,4	4,44	3,86	3,4	2,68	2,4	2,17	1,8	1,3	
All technical information and advice is based on our experience and will be given most conscientiously but without any liability. Indication and figures need to be examined by the user. All sizes are subject to manufacturing tolerances. We reserve the right to modify specifications at any time.													۵ د							

**ProPack Dichtungen** und Packungen AG Rudolf-Diesel-Ring 28 D-82054 Sauerlach Germany

Telefon: +49 8104 6640-0 Telefax: +49 8104 6640-44 Email: propack@propack.ag Internet: http://www.propack.ag

# Distributed by:

### Main areas of application:

- Pumps
- Valves
- Agitators Blenders
- Fittings
  - Stern tubes

· Gate valves

Kneading devices

#### **Characteristics:**

- Volume stable, pressure stable
- · High Cross section density due to special impregnation
- Excellent Value for money
- Graphitised all-round packing with excellent Emergency • run Capabilities
- Good wear resistance against abrasive and crystallizing products
- Recommended shaft Hardness HRC 45 ٠
- · Packing P50A without lubricant for valves, fittings, gate valves

Suitable for:

· Chemical and Paper Industries, Sewage treatment plants, community facilities

Our Purpose: 'To give our customers such exceptional service that they need never consider alternative sources of supply.'